

E S T U D I O P E R S O N A

3469 Casitas Ave.
Los Angeles, CA.
+1 213 522 4798
info@estudiopersona.com

CARE AND MAINTENANCE

Polished Brass
Burnished Brass
Buffed Aluminum
Blackened Brass
Blackened Steel

Use a dry soft cloth to gently go over marks until clean. Do not apply pressure on persistent marks. Remove them using repeated gentle motions and by reapplying with some clean water if necessary. Please note all of our metal products have a clear powdercoat for further protection. Do not use brass cleaners or abrasive pads as they will remove the finish.

Opaline Glass

Wipe gently with a soft cloth and glass cleaner for regular cleaning. All sandblasted glass is luster sealed. Do not use abrasive cleaners or scrubs.

Glass Fiber Reinforced Concrete

Use a lightly damp soft cloth and gently go over any dirt marks until clean. Dry it afterwards with a dry soft cloth. If the concrete is in direct contact with water, please dry immediately to avoid stains.

Solid Wood
Veneer
Lacquered wood

Take a soft cloth that has been dampened with clean water and lightly glide it over the marks until they are removed. Avoid applying pressure to stubborn blemishes; instead, use a series of gentle, repeated motions. Once the cleaning is complete, ensure the wood is dried with a soft cloth to prevent any streaks or scratches.

Oiled Wood

Vacuum the surface or dust gently with a soft cloth. Use a diluted oil cleaner (90% water, 10% cleaner). Clean the surface with a mop or Microfiber Pad. The best working method is with two buckets: one with the soap mixture and one with clean water to rinse the dirt out of the mop. Rinse with clean water. Do not leave water on the surface, it is sufficient to clean damp. Rinse with clean water. Do not leave water on the surface. Allow to dry for \pm 15 minutes.

Fabric

Vacuum regularly, use non-abrasive textile cleaners in order to remove any stains from the fabric.

Leather
Vegetable tanned leather
Suede

If you see some marks or stains please use a dry, soft bristled brush to remove loose debris from the surface of the leather. Do not focus on one area, but rather a complete wipe down moving quickly and evenly.